

CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L335024-70302102-3
Report Reference E335024-20120307
Date 13-Jul-2022

Issued to: PHOENIX CONTACT GmbH & Co. KG
Flachsmarktstrasse 8 Blomberg 32825, Germany

This is to certify that representative samples of DUXR - Communications-, Audio/Video-, Data- and Other Signaling-circuit Accessories
See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 1863, 4th Ed, Issue Date: 2004-05-14, Revision Date: 2019-10-14

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC




Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L335024-70302102-3
Report Reference E335024-20120307
Date 13-Jul-2022

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
NBC, may be followed by -M8, may be followed by -MSD, -MRD, may be followed by /yyy (length), may be followed by -93B, -93C, -963, or -978, may be followed by /R4AC, may be followed by -M8, may be followed by /MSD, /MRD.	Double-Ended Industrial Ethernet Cable Assembly
NBC, may be followed by -M12,, may be followed by -MSD, -MS, -MSX, -MRD, -MRDC1, -MRDC2, -MRDC3, -MRDC4, -MRDC5, -MRDC6, -MRDC7, -MRDC8, -MR, -MRC1, -MRC2, -MRC3, -MRC4, -MRC5, -MRC6, -MRC7, -MRC8, -MRX, -MRXC1, -MRXC2, -MRXC3, -MRXC4, -MRXC5, -MRXC6, -MRXC7 or -MRXC8, may be followed by /yyy (length), may be followed by -93B, -93C, -93E, 93F, -93G, -93H, -93K, -93M, -93R, -94B, -94C, -94F or 94L, may be followed by /R4AQ, /R4AC or R4ACR, may be followed by -M12, may be followed by /FSD, /FS, /FSX, /FRD, /FRDC1, /FRDC2, /FRDC3, /FRDC4, /FRDC5, /FRDC6, /FRDC7, /FRDC8, /FR, /FRC1, /FRC2, /FRC3, /FRC4, /FRC5, /FRC6, /FRC7, /FRC8, /FRX, /MSD, /MS, /MSX, /MRD, /MRDC1, /MRDC2, /MRDC3, /MRDC4, /MRDC5, /MRDC6, /MRDC7, /MRDC8, /MR, /MRC1, /MRC2, /MRC3, /MRC4, /MRC5, /MRC6, /MRC7, /MRC8, or /MRX, may be followed by SCO (1)	Double-ended Industrial Ethernet Cable Assembly
VS-M12MSS,, followed by -M12MSS, -IP20 or -IP20H, followed by -94B or -94F, followed by /yyy (length), followed by 10G or POE	Double-ended Ethernet Cable Assembly



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L335024-70302102-3
Report Reference E335024-20120307
Date 13-Jul-2022

Issued to: PHOENIX CONTACT GmbH & Co. KG
Flachsmarktstrasse 8 Blomberg 32825, Germany

This is to certify that representative samples of DUXR7 - Communications-, Audio/Video-, Data- and Other Signaling-circuit Accessories Certified for Canada
See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: CSA C22.2 NO. 233-17, 3rd Ed., Issue Date: 2017-05-01

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC




Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L335024-70302102-3
Report Reference E335024-20120307
Date 13-Jul-2022

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
NBC, may be followed by -M8, may be followed by -MSD, -MRD, may be followed by /yyy (length), may be followed by -93B, -93C, -963, or -978, may be followed by /R4AC, may be followed by -M8, may be followed by /MSD, /MRD.	Double-Ended Industrial Ethernet Cable Assembly
NBC, may be followed by -M12,, may be followed by -MSD, -MS, -MSX, -MRD, -MRDC1, -MRDC2, -MRDC3, -MRDC4, -MRDC5, -MRDC6, -MRDC7, -MRDC8, -MR, -MRC1, -MRC2, -MRC3, -MRC4, -MRC5, -MRC6, -MRC7, -MRC8, -MRX, -MRXC1, -MRXC2, -MRXC3, -MRXC4, -MRXC5, -MRXC6, -MRXC7 or -MRXC8, may be followed by /yyy (length), may be followed by -93B, -93C, -93E, 93F, -93G, -93H, -93K, -93M, -93R, -94B, -94C, -94F or 94L, may be followed by /R4AQ, /R4AC or R4ACR, may be followed by -M12, may be followed by /FSD, /FS, /FSX, /FRD, /FRDC1, /FRDC2, /FRDC3, /FRDC4, /FRDC5, /FRDC6, /FRDC7, /FRDC8, /FR, /FRC1, /FRC2, /FRC3, /FRC4, /FRC5, /FRC6, /FRC7, /FRC8, /FRX, /MSD, /MS, /MSX, /MRD, /MRDC1, /MRDC2, /MRDC3, /MRDC4, /MRDC5, /MRDC6, /MRDC7, /MRDC8, /MR, /MRC1, /MRC2, /MRC3, /MRC4, /MRC5, /MRC6, /MRC7, /MRC8, or /MRX, may be followed by SCO (1)	Double-ended Industrial Ethernet Cable Assembly



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

